

MX-Sensor_V6.27 Function List For KR Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Abarth | 500C | 2010/01-2019/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Aston Martin | DB11 | 2016/01-2022/12 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS | 2007/09-2015/12 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS Superleggera | 2018/01-2022/12 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | Rapide | 2010/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 2010/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 2010/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 2012/10-2020/12 | 433MHz | AM310 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 2010/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A3 | 2012/06-2021/12 | 433MHz | 8L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A4 | 2012/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A4 | 2008/08-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | A5 | 2006/12-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | A5 | 2019/01-2022/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A6 | 2018/01-2020/12 | 433MHz | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A6 | 2017/07-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | A6 | 2005/01-2018/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A6 | 2002/01-2017/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 아우디 | A7 | 2010/09-2022/12 | 433MHz 5Q0907275 | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A7 | 2012/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | A8 | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A8 | 2010/11-2016/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | A8 | 2009/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | Q5 | 2018/01-2022/12 | 433MHz | 8R | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | Q5 | 2008/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | Q7 | 2005/09-2015/12 | 433MHz | 4L/AU716 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | Q7 | 2015/01-2021/12 | 433MHz | 4L/AU726 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | Q7 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | Q8 | 2018/01-2022/12 | 433MHz | 4M | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | R9 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | R9 | 2009/06-2015/03 | 433MHz 7PP907275F | AU714 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | R9 | 2015/04-2022/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | RS5 | 2017/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | RS5 | 2010/01-2016/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | S6 | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|----------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 아우디 | S6 | 2005/01-2012/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | S6 | 2002/01-2017/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 아우디 | S7 | 2012/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | S8 | 2017/10-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | S8 | 2010/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | S8 | 2009/11-2017/10 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | SQ5 | 2017/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | SQ5 | 2012/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 아우디 | TT | 2014/02-2022/12 | 433MHz | AU334 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | TTS | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 아우디 | e-tron | 2018/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2010/07-2019/07 | 433MHz | F20/F21 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 2008/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 2 Series | 2019/11-2022/12 | 433MHz | F44 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2014/01-2022/12 | 433MHz | F22/F23/F45/F46 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 2017/10-2022/12 | 433MHz | G20 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2014/01-2019/12 | 433MHz | F30/F31/F35 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 2010/10-2014/03 | 433MHz | F30 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2009/09-2014/02 | 433MHz | E9x | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2005/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 2005/01-2009/08 | 433MHz | E9x | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1998/01-2008/06 | 433MHz | E46 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series GT | 2014/03-2021/06 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series Sedan | 2014/03-2019/12 | 433MHz | F34 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 2020/09-2022/12 | 433MHz | G22 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 2013/07-2020/12 | 433MHz | F32/F33/F36 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 5 Series | 2017/01-2022/12 | 433MHz | G30/G31/G38 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 2014/03-2017/12 | 433MHz | F07/F10/F11 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2010/10-2014/02 | 433MHz | F10/F07/F18 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 2017/01-2019/12 | 433MHz | G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series GT | 2014/04-2018/06 | 433MHz | F07 LCI | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 2009/01-2010/12 | 433MHz | E60/E61 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 2009/01-2017/12 | 433MHz | F10/F07 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2014/03-2022/12 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2011/01-2014/03 | 433MHz | F06/F12/F13 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 2016/09-2022/12 | 433MHz | G14/G32 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 2014/03-2015/05 | 433MHz | F01/F02/F03/F04 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2010/10-2015/12 | 433MHz | F01/F02/F04 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2014/10-2022/12 | 433MHz | G11/G12 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 8 Series | 2018/07-2022/12 | 433MHz | G15 | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | M2 | 2014/11-2021/12 | 433MHz | F87 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 2014/01-2019/12 | 433MHz | F80 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M4 | 2014/01-2020/12 | 433MHz | F82/F83 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M5 | 2014/03-2017/12 | 433MHz | F10 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 2010/09-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | M6 | 2014/03-2018/12 | 433MHz | F12 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M8 | 2019/01-2020/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| BMW | 모터사이클 | 2010/01-2019/12 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | X1 | 2015/08-2022/12 | 433MHz | F48 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X1 | 2014/03-2016/06 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2009/01-2013/12 | Indirect | E84 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X2 | 2016/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 2003/01-2010/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 2014/04-2017/12 | 433MHz | F25 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 2017/01-2022/12 | 433MHz | G01/G08 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X4 | 2014/01-2019/12 | 433MHz | F26 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 2017/03-2022/12 | 433MHz | G02 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 2013/05-2019/12 | 433MHz | F15/F85 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 2010/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 2017/09-2022/12 | 433MHz | G05 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X6 | 2008/01-2014/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X6 | 2019/09-2022/12 | 433MHz | G06 | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| BMW | X6 | 2014/08-2019/12 | 433MHz | F16/F86 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X7 | 2018/01-2022/12 | 433MHz | G07 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Z4 | 2018/11-2022/12 | 433MHz | G29 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2009/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | Z4 | 2014/03-2019/02 | 433MHz | E89 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | i Series | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i3 | 2013/01-2022/06 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i8 | 2013/01-2019/12 | 433MHz | I01/I12 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | ix3 | 2020/11-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 벤틀리 | 벤틀가 | 2016/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 벤틀리 | Continental GT | 2005/06-2021/12 | 433MHz BY634 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 벤틀리 | 플라잉 스퍼 | 2019/01-2022/12 | 5Q0907275 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 벤틀리 | 플라잉 스퍼 | 2011/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 벤틀리 | 물산 | 2001/01-2020/12 | 7PP907275F 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 캐딜락 | ATS | 2014/01-2014/12 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS | 2016/01-2020/12 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS | 2013/01-2013/12 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS | 2015/01-2015/12 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS-V | 2015/01-2015/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS-V | 2016/01-2016/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 캐딜락 | ATS-V | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 캐딜락 | BLS | 2006/01-2011/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 캐딜락 | CT7 | 2016/01-2021/12 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | CTS | 2014/01-2015/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | CTS | 2016/01-2021/06 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | CTS | 2013/06-2013/12 | 433MHz | A1LL | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------|-----------------|--------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 캐딜락 | CTS-V | 2010/01-2015/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | CTS-V | 2016/01-2019/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | Colorado | 2020/01-2020/12 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2014/01-2014/12 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2007/01-2008/12 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2009/01-2011/12 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2012/01-2012/12 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2015/01-2020/12 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2021/01-2022/12 | 433MHz 13533166 | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| 캐딜락 | 에스컬레이드 | 2013/01-2013/12 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2008/06-2009/12 | 433MHz 25789964 | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2012/10-2013/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2009/01-2009/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2010/01-2011/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2012/01-2012/09 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2013/01-2013/12 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2014/01-2015/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2014/01-2016/12 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2015/01-2016/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2016/01-2016/12 | 433MHz | C1UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2016/01-2018/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2010/01-2012/12 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2004/01-2006/12 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | SRX | 2007/01-2008/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 캐딜락 | XT4 | 2018/11-2022/12 | 433MHz | E2UL | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 캐딜락 | XT5 | 2018/01-2022/12 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | XT5 | 2016/01-2021/06 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 캐딜락 | XT6 | 2019/01-2022/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | Alpheon | 2011/01-2015/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 아베오 | 2013/01-2018/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 볼트 EV | 2017/01-2020/12 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 카마로 | 2016/01-2016/12 | Snap in 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 카마로 | 2017/01-2020/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 캡티바 | 2011/01-2018/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 콜로라도 | 2017/01-2020/12 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 크루즈 | 2016/01-2019/06 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------|-----------------|-------------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 쉐보레 | 크루즈 | 2013/01-2015/12 | 433MHz | DISC/D1JC/D1WC/KL1J | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 크루즈 | 2012/01-2012/12 | 433MHz | DISC/D1JC/D1WC/KL1J | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 에퀴녹스 | 2017/06-2020/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2013/10-2014/12 | Limited 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2014/01-2020/06 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2015/01-2016/12 | Limited 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2015/01-2016/12 | Limited 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2016/01-2016/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2017/01-2020/06 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2006/01-2006/12 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2007/01-2007/12 | Snap in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2007/01-2007/12 | Clamp in 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2008/01-2008/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2009/01-2011/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2012/01-2012/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 임팔라 | 2013/01-2013/09 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 말리브 | 2017/01-2021/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 말리브 | 2011/01-2016/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 몬테 카를로 | 2007/01-2007/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 올랜도 | 2013/01-2015/12 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 올랜도 | 2016/01-2018/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 스파크 | 2013/01-2020/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | TrailBlazer | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 트래버스 | 2018/01-2022/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 트랙스 | 2013/01-2014/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| 쉐보레 | 트랙스 | 2015/01-2022/12 | 433MHz | G1UC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 쉐보레 | 볼트 | 2016/01-2019/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 200 | 2014/01-2016/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 크라이슬러 | 300C | 2018/01-2021/06 | 18 inch 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 300C | 2018/01-2021/06 | 20 inch 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 300C | 2009/06-2017/12 | 18 inch 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 300C | 2005/06-2009/05 | 433MHz | LE48 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|---------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 크라이슬러 | 300C | 2009/06-2017/12 | 20 inch 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 그랜드 보예저 | 2018/01-2020/03 | 433MHz | RT | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 그랜드 보예저 | 2011/01-2017/12 | 433MHz | RT | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2018/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2006/01-2008/12 | 315MHz | CS | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2004/01-2005/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2003/01-2003/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2004/01-2005/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| 크라이슬러 | 퍼시픽카 | 2016/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Citroen | C4 | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS3 | 2015/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS4 | 2010/01-2014/01 | 433MHz | B75 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 2014/02-2020/12 | 433MHz | B81 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | DS4 Crossback | 2016/01-2020/06 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2011/01-2014/01 | 433MHz | B81 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2014/02-2019/12 | 433MHz | X2/50 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | Space Tourer | 2016/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 페라리 | 458 이탈리아 | 2009/01-2020/12 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 458 Spider | 2009/01-2020/12 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 488 | 2015/01-2021/12 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 575M 마라넬로 | 2002/01-2006/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 595 GTB/GTO | 2004/01-2011/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 599 GTB | 2004/01-2014/12 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 599 GTO | 2004/01-2012/12 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 612 스카글리에티 | 2004/01-2011/12 | 433MHz | F137 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 812 Superfast | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 812 Superfast | 2017/01-2018/12 | 315MHz | | ○ | ● | ○ | C | 315MHz | Huf/Beru | ● | ● |
| 페라리 | CTC4 Lusso T | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 캘리포니아 | 2008/10-2017/12 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 엔조 | 2002/01-2006/12 | 433MHz | F140 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | F12 벨리네타 | 2012/10-2022/12 | 433MHz 282189 | F151/ F152 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | F12 tdf | 2015/01-2021/12 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | F430 | 2007/07-2009/10 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | F430 | 2004/09-2007/06 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | F8 Tributo | 2019/01-2022/12 | 433MHz 282189 | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | FF | 2011/01-2020/01 | 433MHz | F151 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | FXX | 2005/01-2006/12 | 433MHz | F140 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | GTC4 루쏘 | 2016/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | 라 페라리 | 2013/01-2020/12 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | Monza SP1/SP2 | 2019/01-2021/12 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | Portofino | 2017/10-2021/12 | F11001648001 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 페라리 | Portofino | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 페라리 | Roma | 2020/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 페라리 | SF90 Stralade | 2020/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 500 | 2014/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500L | 2012/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 2014/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Freemont | 2014/07-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 포드 | 에스케이프 | 2015/01-2018/12 | 433MHz | C520 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 에스케이프 | 2012/05-2014/12 | 433MHz | C520 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| 포드 | Everest | 2015/01-2018/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 엑스피디션 | 2018/01-2022/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2004/01-2004/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2021/01-2021/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2005/01-2005/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2020/01-2020/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2015/06-2019/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2011/01-2015/12 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2011/01-2015/06 | 433MHz | U502 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| 포드 | 익스플로러 | 2006/01-2010/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 쿠가 | 2014/01-2019/12 | 433MHz | C520 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| 포드 | 몬데오 | 2017/09-2019/05 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 몬데오 | 2013/01-2015/06 | Clamp in 433MHz | CD345 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 포드 | 몬데오 | 2007/01-2012/12 | Clamp in 433MHz | CD345 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 포드 | 몬데오 | 2015/01-2017/08 | Snap in 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 무스탕 | 2019/01-2020/12 | 433MHz | S550 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 무스탕 | 2014/10-2018/12 | 433MHz | S550 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 포드 | 레인저 | 2015/01-2022/12 | Hi Line 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 포드 | 타우러스 | 2016/01-2019/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 혼다 | 아코드 | 2015/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 혼다 | 아코드 | 2013/01-2014/12 | Direct 433MHz | 2GA/2GB/QE | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 혼다 | CR-V | 2014/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 혼다 | 씨빅 | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 혼다 | HR-V | 2014/09-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 혼다 | 오디세이 | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 혼다 | 오디세이 | 2015/01-2016/12 | 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 혼다 | 오디세이 | 2014/01-2017/12 | 315MHz | | ○ | ● | ○ | C | 315MHz | TRW | ● | ● |
| 혼다 | 파이롯 | 2016/01-2017/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 혼다 | 파이롯 | 2009/01-2015/12 | Alloy 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| 혼다 | 파이롯 | 2009/01-2015/12 | Steel 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| 혼다 | 파이롯 | 2018/01-2021/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 흠머 | H2 | 2008/01-2008/12 | 315MHz 15922396 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| 흠머 | H2 | 2007/01-2007/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 현대 | H2 | 2009/01-2010/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| 현대 | H2 | 2008/01-2008/12 | 315MHz 13598771 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| 현대 | H3 | 2007/01-2010/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| 현대 | H3 | 2006/01-2006/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| 현대 | H3T | 2006/01-2010/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| 현대 | 엑센트 | 2015/01-2018/12 | Lo Line 433MHz | RB | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 엑센트 | 2015/01-2018/12 | Hi Line 433MHz | RB | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Aslan | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Aslan | 2014/01-2017/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Avante | 2016/01-2020/12 | AD 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Avante | 2012/01-2016/12 | JK 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | Avante | 2014/01-2016/12 | MD 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | Avante | 2011/01-2013/12 | MD 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | EQ900 | 2016/01-2017/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| 현대 | 엘란트라 | 2013/10-2019/12 | Lo Line 315MHz | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| 현대 | Elantra GT | 2017/06-2021/12 | 433MHz | PD | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 에쿠스 | 2013/01-2016/12 | 433MHz | VI New | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 현대 | 에쿠스 | 2008/01-2013/12 | 433MHz | VI Old | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | 제네시스 | 2007/01-2007/12 | 315MHz | BH | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| 현대 | 제네시스 | 2013/01-2016/12 | 433MHz | DH | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 현대 | 제네시스 | 2013/01-2016/12 | 315MHz | BK | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| 현대 | 제네시스 | 2007/01-2014/12 | 433MHz | BH | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | Genesis Coupe | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis Coupe | 2012/01-2013/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis G70 | 2018/01-2021/12 | 433MHz | IK | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| 현대 | Genesis G70 | 2017/01-2017/12 | 433MHz | IK | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| 현대 | Genesis G80 | 2020/01-2021/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis G80 | 2016/07-2022/12 | 433MHz | DH | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis G90 | 2019/01-2022/12 | 433MHz | HI | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis G90 | 2016/01-2018/12 | 433MHz | HI | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis GV70 | 2020/12-2022/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Genesis GV80 | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| 현대 | Grand Starex | 2015/01-2020/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 그랜저 | 2018/01-2019/12 | 433MHz | IG LAMBDA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 그랜저 | 2020/01-2021/12 | 433MHz | IG LAMBDA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 그랜저 | 2015/01-2017/12 | Hybrid 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 그랜저 | 2014/01-2014/12 | Hybrid 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | 그랜저 | 2011/06-2015/12 | HG 433MHz | | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | 그랜저 | 2011/01-2017/12 | DM 433MHz | HG | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| 현대 | 그랜저 | 2017/01-2020/12 | 433MHz | IG/IG HEV | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | 이오닉 | 2016/01-2021/12 | 433MHz | AE | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| 현대 | Ioniq 5 | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 현대 | Kona | 2017/01-2021/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| 현대 | Maxcruz | 2012/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Mohave | 2020/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Nexo | 2018/04-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 현대 | Palisade | 2019/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | Porter | 2014/01-2020/12 | HR 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Porter | 2007/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 싼타페 | 2006/01-2008/12 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| 현대 | 싼타페 | 2009/01-2012/05 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| 현대 | 싼타페 | 2012/01-2015/12 | 433MHz | DM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 싼타페 | 2012/06-2014/12 | 315MHz | NC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| 현대 | 싼타페 | 2018/01-2018/12 | 433MHz | TM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | 싼타페 | 2019/01-2020/12 | 433MHz | TM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | Solati | 2014/03-2019/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 쏘나타 | 2014/04-2019/12 | Hi Line 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | 쏘나타 | 2014/01-2015/12 | VDO 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 쏘나타 | 2010/01-2010/12 | 433MHz | YF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 쏘나타 | 2010/01-2013/12 | 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Sonata Hybrid | 2016/01-2019/12 | 433MHz | YF/LF HEV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | Sonata Hybrid | 2011/01-2019/12 | 529331J000 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Sonata Hybrid | 2011/01-2014/12 | 529333N100 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 스타렉스 | 2007/01-2015/12 | 433MHz | A1 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| 현대 | 스타렉스 | 2007/01-2007/12 | 315MHz | | ○ | ● | ○ | C | 315MHz | Continental | ● | ● |
| 현대 | 투싼 | 2016/01-2017/12 | 433MHz | TL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 현대 | 투싼 | 2012/01-2015/12 | Hi line 433MHz | LM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 현대 | 투싼 | 2009/01-2013/12 | 433MHz | LM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 현대 | 투싼 | 2015/05-2021/09 | Hi Line 433MHz | TL | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | 투싼 | 2015/01-2018/12 | 433MHz | LM FCEV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | 투싼 | 2012/01-2015/12 | Lo Line 433MHz | LM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 현대 | 투싼 | 2021/01-2021/12 | 433MHz | NX | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 현대 | 벨로스터 | 2011/03-2019/06 | 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 현대 | 벨로스터 | 2018/01-2022/12 | 433MHz | JS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | Venue | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 현대 | 베라크루즈 | 2007/01-2012/12 | CM 433MHz | EN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | 베라크루즈 | 2007/01-2013/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| 현대 | i30 | 2012/01-2016/12 | 433MHz | GD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 현대 | i30 | 2017/01-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 현대 | i30 | 2016/08-2022/12 | 433MHz | PD/Pde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | i40 | 2017/01-2019/12 | 433MHz | IF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 현대 | i40 | 2014/04-2020/12 | 433MHz | VF | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| 현대 | i40 | 2011/01-2014/03 | 433MHz | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 인피니티 | EX Series | 2007/01-2014/03 | 433MHz | P53B/J50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 인피니티 | FX Series | 2008/03-2015/04 | 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 인피니티 | G Series | 2006/01-2014/02 | 433MHz | CV36/G312/L53A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 인피니티 | M Series | 2009/12-2016/04 | 433MHz | M312/Y51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 인피니티 | Q30 | 2015/01-2021/12 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 인피니티 | Q50 | 2013/01-2020/12 | 433MHz | L53H/D53H/V37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 인피니티 | Q60 | 2016/05-2021/12 | 433MHz | CV37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 인피니티 | Q70 | 2013/01-2021/12 | 433MHz | L53E | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 인피니티 | Q70 | 2018/10-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 인피니티 | QX50 | 2017/11-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 인피니티 | QX60 | 2012/02-2022/12 | 433MHz | L50 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 인피니티 | QX70 | 2013/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 인피니티 | QX70 | 2014/01-2020/06 | PAC 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 인피니티 | QX80 | 2010/01-2016/09 | 433MHz | JA60 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 인피니티 | QX80 | 2013/01-2022/12 | 433MHz | Z62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 재규어 | E-페이스 | 2017/01-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | F-페이스 | 2015/01-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | F-타입 | 2017/01-2023/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | F-타입 | 2014/01-2015/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 재규어 | I-페이스 | 2017/01-2023/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XE | 2014/01-2015/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 재규어 | XE | 2015/01-2022/06 | GX631A159AA 433MHz | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XF | 2015/06-2022/12 | 433MHz | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XF | 2014/07-2015/05 | 433MHz | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XF | 2008/01-2014/06 | 433MHz | X250 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XJ | 2016/01-2022/12 | 433MHz | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XJ | 2010/01-2015/12 | 433MHz | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XK | 2005/09-2015/12 | 433MHz | X150 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 재규어 | XKR | 2006/01-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 지프 | 체로키 | 2017/01-2017/12 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| 지프 | 체로키 | 2018/01-2020/06 | 433MHz | KL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| 지프 | 체로키 | 2014/01-2016/12 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| 지프 | 컴맨더 | 2006/01-2007/12 | 433MHz | XK | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 컴맨더 | 2008/01-2010/12 | 433MHz | XK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | 컴파스 | 2008/01-2009/12 | 315MHz | MK49 | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| 지프 | 컴파스 | 2018/01-2018/12 | 433MHz | 551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 컴파스 | 2017/01-2017/12 | 433MHz | 551 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 컴파스 | 2014/09-2017/12 | 433MHz | MK49 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | 컴파스 | 2007/01-2007/12 | 315MHz | MK49 | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| 지프 | 컴파스 | 2006/05-2014/08 | 433MHz | MK49 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | Gladiator | 2019/11-2022/12 | MRXAG4WA5 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | 그랜드 체로키 | 2016/01-2022/12 | 433MHz 68252493AB | WK | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 그랜드 체로키 | 2014/01-2015/12 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| 지프 | 그랜드 체로키 | 2016/01-2017/12 | 433MHz | WK | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 지프 | 그랜드 체로키 | 2011/01-2011/12 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| 지프 | 그랜드 체로키 | 2012/01-2013/12 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| 지프 | 패트리오트 | 2007/01-2008/12 | 433MHz | MK | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 패트리오트 | 2009/01-2014/12 | 315MHz | MK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| 지프 | 레니게이드 | 2015/01-2016/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 레니게이드 | 2017/01-2017/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 레니게이드 | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 레니게이드 | 2020/01-2022/12 | 433MHz 53394085 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 지프 | 랭글러 | 2010/01-2013/12 | 433MHz | JK72 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | 랭글러 | 2014/01-2017/12 | 433MHz | JL | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| 지프 | 랭글러 | 2018/01-2021/06 | 433MHz | JL | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 기아 | Bongo | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Bongo | 2017/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Bongo | 2020/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 카렌스 | 2014/01-2019/12 | 433MHz | RP | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | 카니발 | 2018/01-2018/12 | 52933C1100 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | 카니발 | 2020/01-2021/12 | 433MHz | KA4 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | 카니발 | 2014/01-2018/12 | Sedan 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | 카니발 | 2005/01-2014/12 | 315MHz | YP | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| 기아 | 카니발 | 2019/01-2019/12 | 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | EV6 | 2021/03-2027/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | K3 | 2019/01-2021/12 | 433MHz Pacific | BDC/BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| 기아 | K3 | 2012/01-2019/12 | 433MHz TRW | YDC/YD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | K3 | 2012/01-2016/12 | 529333X305 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | K5 | 2020/01-2020/12 | 433MHz | DL3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | K5 | 2015/07-2020/05 | Hybrid 433MHz | JF/JF HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | K5 | 2013/01-2015/06 | Hybrid 433MHz | TF/TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | K5 | 2011/01-2012/12 | 433MHz | TF/TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | K7 | 2016/01-2019/12 | 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | K7 | 2013/01-2016/12 | Hybrid 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | K7 | 2008/01-2012/12 | 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | K9 | 2019/01-2020/12 | 433MHz | RJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | K9 | 2011/01-2018/12 | 433MHz | KH | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | 모하비 | 2020/01-2020/12 | 433MHz | HM PE2 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 모하비 | 2016/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 모하비 | 2014/09-2015/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| 기아 | 모하비 | 2008/01-2014/08 | 433MHz | | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| 기아 | 모하비 | 2007/01-2007/12 | 433MHz | HM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | 모하비 | 2007/01-2007/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | 모닝 | 2014/01-2019/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Morning 3 | 2017/01-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 기아 | 니로 | 2016/01-2021/12 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Opirus | 2006/01-2014/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Pride | 2018/01-2018/12 | Lo Line 433MHz | YB | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Pride | 2018/01-2018/12 | Hi Line 433MHz | YB | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Pride | 2017/01-2018/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 기아 | Pride | 2012/01-2017/12 | UB 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Ray | 2011/01-2020/12 | Elec 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Seltos | 2019/01-2021/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | Sonet | 2021/01-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 기아 | 쏘렌토 | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘렌토 | 2014/01-2018/06 | 433MHz 529333N100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘렌토 | 2011/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘렌토 | 2009/01-2010/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘렌토 | 2006/01-2008/12 | 433MHz | XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘렌토 | 2020/01-2021/12 | 433MHz | MQ4 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | 쏘울 | 2008/06-2013/10 | 433MHz | AM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘울 | 2019/01-2022/12 | 433MHz | SK3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | 쏘울 | 2013/11-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | 스포티지 | 2013/10-2016/01 | 433MHz | SL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| 기아 | 스포티지 | 2015/11-2021/06 | 433MHz | QL/QLE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 기아 | 스포티지 | 2010/01-2013/12 | Lo Line 433MHz | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | 스포티지 | 2010/01-2014/01 | Hi Line 433MHz | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Sportage R | 2014/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| 기아 | Stinger | 2017/06-2017/12 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | Stinger | 2017/01-2017/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | Stinger | 2018/01-2022/12 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 기아 | Stonic | 2017/11-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 기아 | Stonic | 2017/01-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 람보르기니 | 아벤타도 | 2011/01-2022/12 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 람보르기니 | Few Off | 2017/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 람보르기니 | 허라칸 | 2014/01-2022/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 람보르기니 | One off | 2016/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 람보르기니 | Urus | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 랜드로버 | 디펜더 | 2019/01-2023/06 | 433MHz LR070840 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 디스커버리 | 2017/01-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 디스커버리 | 2015/10-2016/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 디스커버리 | 2004/07-2016/12 | KR5S18005202 OA 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 랜드로버 | 디스커버리 스포츠 | 2015/09-2020/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 디스커버리5 | 2019/01-2020/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 랜드로버 | 프리랜더 | 2006/01-2022/06 | 433MHz | Fr132 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 | 2015/06-2022/12 | 433MHz | D6, Ra5 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-----------|-----------------|--------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 랜드로버 | 렌지로버 | 2010/01-2015/12 | 433MHz | L322 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 에보크 | 2015/10-2022/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 에보크 | 2011/01-2015/09 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 스포츠 | 2015/06-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 스포츠 | 2013/01-2015/05 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 랜드로버 | 렌지로버 벨라 | 2017/01-2023/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 렉서스 | CT Series | 2010/12-2021/12 | 433MHz | 080A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | ES Series | 2012/06-2018/05 | 433MHz | 980L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | ES Series | 2018/06-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | ES Series | 2006/01-2012/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | GS Series | 2012/01-2021/12 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | IS Series | 2013/04-2021/12 | 433MHz | 030L/400A/720A/XE30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | IS Series | 2006/01-2015/07 | PMV-107J 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| 렉서스 | LC Series | 2017/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | LS Series | 2012/10-2017/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | LS Series | 2017/10-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | LX Series | 2015/10-2021/12 | PMVC215 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | NX Series | 2014/01-2022/12 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | RC Series | 2014/01-2022/12 | 433MHz | XC1/720A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | RX Series | 2015/11-2021/12 | C215 433MHz | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | RX Series | 2013/01-2015/10 | 433MHz | 640L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 렉서스 | RX Series | 2015/10-2020/12 | C015 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| 렉서스 | UX Series | 2018/01-2021/12 | 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 링컨 | 에비에이터 | 2020/01-2020/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 링컨 | 컨티넨탈 | 2017/01-2020/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 링컨 | Corsair | 2019/08-2020/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| 링컨 | MKC | 2015/06-2018/12 | 433MHz | 2. OF SEL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 링컨 | MKX | 2015/01-2015/12 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| 링컨 | MKX | 2016/01-2019/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 링컨 | MKZ | 2013/01-2016/12 | 433MHz DR3V1A180DA | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 링컨 | MKZ | 2015/09-2020/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| 링컨 | Nautilus | 2019/01-2020/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lotus | 3 Eleven | 2015/01-2021/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 2000/09-2021/05 | 433MHz | Monza | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 2010/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Exige | 2000/09-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 마세라티 | 지블리 | 2013/01-2020/12 | 433MHz | M156/M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 마세라티 | 그란싸브리오 | 2017/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 마세라티 | 그란 투리스모 | 2014/01-2022/01 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 마세라티 | 레반테 | 2020/01-2021/12 | 433MHz | M161 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| 마세라티 | 레반테 | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 마세라티 | MC20 | 2020/01-2021/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------------|-----------------|---------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 마세라티 | 콰트로폴테 | 2013/01-2018/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| McLaren | 500 Series | 2015/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 2014/03-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 2017/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | GT | 2019/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 2013/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 2018/01-2020/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 2019/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 메르세데스-벤츠 | A Class | 2018/06-2022/06 | 433MHz | W177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 메르세데스-벤츠 | A Class | 2014/04-2018/05 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | A Class | 2012/01-2014/03 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | AMG GT | 2014/01-2022/06 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | B Class | 2011/11-2019/01 | 433MHz | W246/W242 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | C Class | 2018/01-2018/12 | 433MHz | C205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | C Class | 2018/06-2020/12 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | C Class | 2014/03-2018/05 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | C Class | 2007/04-2014/02 | 433MHz | W204/W203 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | CLA Class | 2019/05-2022/12 | 433MHz | C118 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 메르세데스-벤츠 | CLA Class | 2014/06-2019/04 | 433MHz | C117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | CLA Class | 2012/12-2014/05 | 433MHz | C117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | CLS Class | 2017/01-2022/12 | 433MHz | C257 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | CLS Class | 2012/01-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | E Class | 2009/07-2014/05 | 433MHz | W212/C207 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | E Class | 2005/06-2011/10 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 메르세데스-벤츠 | E Class | 2015/11-2022/12 | 433MHz | W213/BR238 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | E Class | 2014/06-2018/12 | 433MHz | W212 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | EQC | 2019/05-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | G Class | 2007/04-2018/05 | 433MHz | G463/461 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | G Class | 2018/06-2022/12 | 433MHz | G463 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLA Class | 2018/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLC Class | 2015/01-2019/07 | 433MHz | X253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLC Class | 2019/08-2022/07 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLE Class | 2015/07-2020/12 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLE Class | 2018/10-2022/12 | 433MHz | V167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 메르세데스-벤츠 | GLK Class | 2008/01-2015/09 | 433MHz | X204 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GLS Class | 2013/01-2019/06 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | GT | 2014/01-2022/12 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | S Class | 2017/01-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | S Class | 2020/01-2022/12 | 433MHz | W223 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | S Class | 2013/07-2020/12 | 433MHz | W222/C217 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | S Class | 2009/06-2013/06 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | SL Class | 2012/01-2020/12 | 433MHz | W231 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | SLC Class | 2016/01-2020/06 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 메르세데스-벤츠 | SLK Class | 2004/01-2021/12 | 433MHz | R171, R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 미니 | 3-5 Doors Hatch | 2014/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 클럽맨 | 2013/11-2021/12 | 433MHz | F54 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-------------------|--------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 미니 | 클럽맨 | 2008/01-2013/12 | Indirect | R55 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 미니 | Convertible | 2014/01-2016/12 | 433MHz | R57 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 미니 | Convertible | 2010/01-2013/12 | Indirect | R57 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 미니 | Convertible | 2017/01-2021/12 | 433MHz | R57 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 쿠퍼 | 2014/03-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 컨트리맨 | 2010/01-2013/12 | Indirect | R60 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 미니 | 컨트리맨 | 2014/07-2018/12 | 433MHz | R60 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 미니 | 컨트리맨 | 2015/07-2022/12 | 433MHz | F60 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 쿠페 | 2014/01-2015/12 | 433MHz | R58 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 미니 | 쿠페 | 2016/01-2017/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 쿠페 | 2012/01-2013/12 | Indirect | R58 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 미니 | 해치백 | 2013/11-2019/12 | 433MHz | F56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| 미니 | 페이스맨 | 2012/01-2013/12 | Indirect | R61 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 미니 | 페이스맨 | 2014/07-2018/06 | 433MHz | R61 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 미니 | 로드스터 | 2014/01-2015/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 미니 | 로드스터 | 2012/01-2013/12 | Indirect | R59 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 니산 | 370Z | 2013/07-2021/06 | PAC 433MHz | RC53D(2)/Z34 | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| 니산 | 370Z | 2008/01-2014/07 | 433MHz | C53D/Z34 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 니산 | 알티마 | 2018/10-2022/12 | 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 알티마 | 2012/05-2019/09 | 407003JA0B 433MHz | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | Altima Sedan | 2006/01-2012/12 | 315MHz | L33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| 니산 | GT-R | 2007/01-2022/12 | 315MHz | R35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| 니산 | 쥬크 | 2014/03-2019/12 | 407005ZH0A 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 니산 | 리프 | 2017/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 리프 | 2010/10-2019/12 | 433MHz | ZE0/B12G | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 니산 | Leaf Korea | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 맥시마 | 2015/04-2021/12 | Clamp in 433MHz | A36 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 맥시마 | 2019/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 무라노 | 2014/01-2014/12 | 433MHz | Z51/Z52/P42M | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 니산 | 무라노 | 2013/10-2022/12 | Clamp in 433MHz | Z52 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 무라노 | 2008/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 니산 | 패스파인더 | 2015/11-2020/12 | 433MHz | R52/P61B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 니산 | 엑스트레일 | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 푸조 | 1007 | 2004/01-2011/12 | 433MHz | A08/PF1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 푸조 | 2008 | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 푸조 | 208 | 2012/05-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 푸조 | 208 | 2002/01-2002/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| 푸조 | 3008 | 2013/09-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 푸조 | 3008 | 2008/11-2013/08 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 푸조 | 308 | 2013/09-2019/12 | 9802003680 433MHz | T7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 푸조 | 308 | 2014/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 푸조 | 308 | 2007/04-2015/08 | 5430W0 433MHz | T7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 푸조 | 407 | 2003/01-2012/12 | 433MHz | D2 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 푸조 | 5008 | 2009/01-2013/08 | 433MHz | T87 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 푸조 | 508 | 2013/10-2019/12 | 433MHz | W2 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| 푸조 | 508 | 2010/01-2014/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 푸조 | 607 | 2004/10-2012/12 | 433MHz | Z8 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 푸조 | 807 | 2004/10-2016/12 | 433MHz | V2/80092 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 포르쉐 | 718 (982) | 2016/01-2021/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 | 2015/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 | 2012/02-2016/12 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 | 2011/01-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 | 2005/01-2012/12 | 315MHz | 997 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 | 2004/07-2012/01 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (991) | 2011/12-2016/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (991) | 2011/01-2016/12 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (992) | 2017/01-2021/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (997) | 2005/02-2008/03 | 433MHz | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (997) | 2005/01-2008/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (997) | 2015/09-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (997) | 2009/01-2015/08 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (997) | 2008/04-2015/08 | 433MHz | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (터보) | 2007/01-2009/12 | 433MHz | 997T | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (터보) | 2007/01-2009/12 | 315MHz | 997T | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (터보) | 2010/01-2016/12 | 433MHz | 991T | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 911 (터보) | 2010/01-2016/12 | 315MHz | 991T | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 918 스파이더 | 2013/01-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2004/01-2008/12 | 315MHz | 987 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2009/01-2012/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2009/01-2013/12 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2012/01-2016/12 | 433MHz | 981 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2012/01-2016/12 | 315MHz | 981/981SP | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2016/03-2022/06 | 433MHz | 982/982SP | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2017/01-2021/12 | 315MHz | 982/982SP | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 박스터 | 2004/01-2008/12 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | Carrera GT | 2003/09-2011/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2017/09-2022/12 | 433MHz | 9YA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2015/01-2021/12 | 315MHz | 9YA | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2014/11-2017/08 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2011/01-2014/10 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2010/01-2014/12 | 315MHz | 92A | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2007/01-2010/12 | 433MHz | 9PA1 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2007/01-2010/12 | 315MHz | 9PA1 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2002/01-2006/12 | 433MHz | 9PA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 카이엔 | 2002/01-2006/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | Cayenne S | 2017/09-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 포르쉐 | Cayenne S | 2014/06-2017/08 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | Cayenne S | 2010/01-2014/05 | 433MHz | 4. 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | Cayenne S | 2010/01-2012/12 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | Cayenne S | 2008/01-2009/12 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | Cayenne S | 2007/01-2009/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2009/01-2011/12 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2009/01-2012/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2012/01-2016/12 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2005/01-2008/12 | 433MHz | 987/987C | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2005/01-2008/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2016/10-2022/06 | 433MHz | 982/982C/CT 4-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 케이맨 | 2013/01-2016/12 | 315MHz | 2. 7L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | GT3 | 2010/01-2016/12 | 433MHz | 996/997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | GT3 | 2006/03-2011/12 | 433MHz | 996 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | GT3 | 2007/01-2009/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | GT3 | 2015/01-2015/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | GT3 | 2017/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 마칸 | 2018/01-2021/12 | 315MHz | 95B | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 마칸 | 2014/01-2017/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 마칸 | 2014/01-2021/12 | 433MHz | P0416/95B | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 파나마메라 | 2013/09-2017/08 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 파나마메라 | 2010/01-2013/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | 파나마메라 | 2009/01-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 파나마메라 | 2017/09-2021/06 | 433MHz | 970/971 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | 파나마메라 | 2014/01-2016/12 | 315MHz | 970 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | Panamera S | 2009/01-2013/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| 포르쉐 | Panamera S | 2009/06-2013/12 | 315MHz | 4. 8L | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| 포르쉐 | Taycan | 2019/01-2022/12 | 433MHz 9J1907275 | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Renault | Clio | 2013/01-2015/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Renault | Clio III | 2004/04-2014/05 | 433MHz | X85 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 2014/06-2019/12 | 433MHz | X85/X98 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Master | 2009/11-2021/06 | 433MHz | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Zoe | 2019/07-2021/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | QM3 | 2016/01-2018/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 르노삼성 | QM3 | 2013/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 르노삼성 | QM5 | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | QM5 | 2009/01-2013/12 | 315MHz | | ○ | ● | ○ | C | 315MHz | Schrader | ● | ● |
| 르노삼성 | QM5 | 2007/01-2013/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| 르노삼성 | QM6 | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM3 | 2017/01-2020/12 | 407004CBOA 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| 르노삼성 | SM3 | 2009/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM3 ZE | 2015/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM5 | 2016/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 르노삼성 | SM5 | 2010/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM6 | 2015/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM7 | 2016/01-2020/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | SM7 | 2012/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| 르노삼성 | XM3 | 2019/01-2020/12 | 433MHz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| 롤스로이스 | Cullinan | 2018/01-2021/12 | 433MHz | R31 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 롤스로이스 | 다운 | 2016/01-2021/12 | 433MHz | RR6 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 롤스로이스 | 고스트 | 2020/01-2021/06 | 433MHz | RR21 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 롤스로이스 | 고스트 | 2010/01-2020/12 | 433MHz | RR04 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 롤스로이스 | 팬텀 | 2017/01-2022/12 | MRXAG5SP4 433MHz | RR11 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 롤스로이스 | 팬텀 | 2012/01-2017/12 | 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 롤스로이스 | 컬리넌 | 2013/08-2022/12 | 433MHz | RR5 | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 엑티온 | 2013/01-2021/12 | QJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 엑티온 | 2018/07-2019/12 | Q200 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 체어맨 | 2005/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 쌍용 | 체어맨 | 2014/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 체어맨 | 2014/01-2019/12 | 4199034000 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 코란도 | 2008/01-2013/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 쌍용 | 코란도 | 2012/01-2019/12 | C200 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 코란도 | 2019/05-2022/06 | 4199037000 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 카이런 | 2006/01-2014/05 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 쌍용 | 카이런 | 2014/01-2016/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 무쏘 | 2018/06-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 무쏘 | 2016/01-2018/05 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 렉스턴 | 2020/01-2021/12 | C300 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 렉스턴 | 2017/03-2022/12 | Y400 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 렉스턴 | 2014/01-2017/12 | Y300 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | 렉스턴 | 2006/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 쌍용 | Rodius | 2014/01-2021/12 | AJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | Rodius | 2005/01-2013/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| 쌍용 | 티볼리 | 2019/06-2021/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | 티볼리 | 2015/01-2020/06 | X100 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 쌍용 | Turismo | 2014/01-2022/12 | AJ 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| 쌍용 | XLV | 2016/01-2021/12 | XK 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 테슬라 | Model 3 | 2016/01-2020/08 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 테슬라 | Model 3 | 2018/01-2021/12 | 433MHz (10748 1200B) | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 테슬라 | Model S | 2014/09-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 테슬라 | Model X | 2014/10-2022/12 | Continental 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| 도요타 | 86 | 2012/04-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 아발론 | 2013/01-2018/04 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 아발론 | 2018/04-2020/12 | 433MHz | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 캠리 | 2016/01-2022/12 | C215 433MHz | 045L | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| 도요타 | 캠리 | 2014/01-2017/12 | 433MHz | XV50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------------|-----------------|------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 도요타 | Camry Hybrid | 2014/01-2017/09 | 433MHz | XV50/XV70 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | FJ 크루저 | 2014/06-2020/12 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | GR Supra | 2019/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| 도요타 | GT86 | 2012/09-2022/12 | 433MHz | E88 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 랜드크루저 | 2014/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | Land Cruiser Prado | 2009/01-2017/09 | 433MHz | 611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 프리우스 | 2019/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 프리우스 | 2014/01-2018/12 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 프리우스 C | 2014/03-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 프리우스 V | 2014/11-2017/11 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | RAV4 | 2012/01-2019/09 | 433MHz | 410A/XA40/120L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | RAV4 | 2018/01-2021/12 | 433MHz | XA50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 씨에나 | 2010/06-2020/12 | 433MHz | 500N/500L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 도요타 | 벤자 | 2014/06-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| 폭스바겐 | 아테온 | 2017/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 비틀 | 2012/12-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 비틀 | 2012/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 폭스바겐 | CC | 2011/06-2017/12 | 433MHz | VC17 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | CC | 2018/01-2021/12 | MQB 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | EOS | 2014/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 폭스바겐 | 골프 | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 폭스바겐 | 골프 | 2012/01-2012/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| 폭스바겐 | 제타 | 2010/01-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 폭스바겐 | 뉴 비틀 | 2012/01-2022/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 폭스바겐 | 뉴 비틀 | 2011/08-2020/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 파사트 | 2014/09-2021/06 | 433MHz | B8 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 파사트 | 2010/01-2014/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 파사트 | 2005/01-2011/12 | 433MHz | VW451 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 폭스바겐 | 페이톤 | 2010/06-2019/12 | 433MHz | Vh67 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 페이톤 | 2001/12-2007/05 | 433MHz | VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 폴로 | 2009/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 폭스바겐 | 티구안 | 2016/01-2020/12 | 433MHz | VW376/5N2 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 티구안 | 2011/05-2015/12 | 433MHz | 5N | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 투아렉 | 2014/08-2022/12 | 433MHz | 7P5/7P6108 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 폭스바겐 | 투아렉 | 2010/01-2014/07 | 433MHz | VW526 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| 볼보 | C30 | 2011/01-2014/03 | 433MHz | Y279 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C30 | 2006/01-2010/12 | 433MHz | Y279 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C30 일렉트릭 | 2011/01-2013/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C30 일렉트릭 | 2010/01-2010/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C70 | 2011/01-2014/06 | 433MHz | V70064 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C70 | 2008/01-2010/12 | 433MHz | V70064 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | C70 | 2006/01-2007/12 | 433MHz | V70064 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| 볼보 | S40 | 2011/01-2014/06 | 433MHz | V40044 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| 볼보 | S40 | 2003/01-2010/12 | 433MHz | V40044 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | S60 | 2018/01-2021/06 | 433MHz | V431 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 볼보 | S60 | 2014/07-2020/12 | 433MHz | Y283 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | S60 | 2013/02-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | S60 | 2010/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| 볼보 | S60 | 2010/01-2013/01 | 433MHz | Y283 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | S80 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | S80 | 2006/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| 볼보 | S80 | 2006/01-2013/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | S90 | 2016/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | S90 | 2016/01-2021/06 | 433MHz | V541 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 볼보 | V40 | 2015/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | V40 | 2012/01-2020/12 | 433MHz | Y555, Y556 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V50 | 2011/01-2016/12 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V50 | 2003/01-2010/12 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V60 | 2017/11-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 볼보 | V60 | 2015/09-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | V60 | 2014/01-2019/12 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V60 | 2008/01-2014/06 | 433MHz | Y352 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V70 | 2007/01-2016/12 | 433MHz | Y285 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | V90 | 2016/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | V90 | 2015/01-2022/12 | 433MHz | V542 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 볼보 | XC40 | 2017/01-2022/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | XC60 | 2015/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | XC60 | 2008/01-2021/06 | 433MHz | Y413 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | XC70 | 2014/07-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | XC70 | 2010/01-2014/06 | 433MHz | Y381 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | XC70 | 2008/01-2009/12 | 433MHz | Y381 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| 볼보 | XC90 | 2016/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| 볼보 | XC90 | 2015/01-2021/06 | 433MHz | V526 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| 볼보 | XC90 | 2005/01-2014/12 | 433MHz | Y289 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |